

Royce Too LLC Children's Product Certificate

| Product Description: | Children's Socks made of Polyester, Sorbtek, Nylon and Spandex | | |
|---|--|-------------|------------|
| Style #: | C61004M,L | C61006M,L | C621006M,L |
| Purchase Order #: | 400542 | | |
| Importer of Record: | Royce Too LLC 3330 Healy Drive | | |
| | | | |
| | Suite 200 | | |
| | Winston Salem | n, NC 27103 | |
| | (336)-355-739 | 0 | |
| Contact information for the individual maintaining records of test results: | | | |
| Name: Sadina Salcinovic | | | |
| Address: 3330 Healy Drive, Suite 200, Winston Salem, NC 27103 | | | |
| Email: ssalcinovic@roycetoo.cc | om | | |
| Talanhana number (22C) 255 72C2 | | | |

Telephone number: (336)-355-7363

Place of Manufacture: Zhuji, Zhejiang, China

Month and Year of Manufacture: 04/23

Citation to each CPSC Product Safety Regulation to which this product is being certified:

- (i) 16 CFR part 1610 Standard for the Flammability of Clothing Textiles
- (ii) 15 U.S.C 1278a Total lead content requirements

Date and place where this product was tested for compliance with the regulation(s) cited above: No testing is required for:

(i) Flammability requirements 16 CFR part 1610: Exemption 16 CFR 1610.1(d)(1) socks made of plain surface fabric, weighing 2.6 ounces per square yard or more, regardless of fiber content; and exemption 16 CFR 1610.34 only uncovered or exposed parts of wearing apparel shall be tested under the standard.

Note: Cushioned socks are not intended to be worn inside out. The raised surface is not intended to be exposed.

(ii) Total lead content requirements 15 U.S.C 1278a: Exemption 16 CFR 1500.91 dyed and undyed textiles that are not treated or adulterated, which means such materials do not need to be tested for total lead content.

The CPSC-accepted third party where this product was tested by an accredited laboratory for compliance with the regulation(s) cited above: Not applicable